

BCIN-12886

Date July 26/23

Orser Farm & Septic Pumping
1059848 Ontario Inc.
4657 Bellrock road
Verona Ont
K0h 2w0
613-374-2031

Letter of inspection-

Client name-

Jeff Brown

Address-

4227 Maple Drive

The following, have been inspected, and found to be in proper working order.

- The septic tank was pumped out, and inspected for any cracks.
- The condition of the partition in the tank was inspected.
- The two baffles, one at each end of the tank were inspected.
- The waste level in the tank was at the proper working level.
- The area of the tilebed was inspected. At this time there was no evidence of any leakage of biomat present, **However we cannot inspect what we cannot see (underground). Therefore we cannot confirm that all is in proper working order in the tilebed, under the ground.**

Comments-

Older system app 50 yrs old
good working order when pumped

If you have any questions, contact us at 613-374-2031

Yours Truly-

