

Well Testing & Consulting



John Jeffery

Phone: (343) 989 2377

johndjeffery@yahoo.ca

800 Larchwood Cres., Kingston ON

July 14, 2026

WELL TEST AND INSPECTION REPORT

Property Address: 11703 Highway 41

A well inspection was conducted at the above-referenced property. The water source is a drilled well with a measured depth of 65 feet and static level found at 14 feet at time of inspection.

A flow test was performed at a pumping rate of 10 gallons per minute while monitoring drawdown and recovery. There was no drop in pumping pressure or volume. It was determined that this well is currently making a minimum of 10 gallons per minute at this time.

Water Quality Results:

Parameter	Raw Water	Treated Water
Iron	1.5	1.5
Sulfur	0	0
Hardness	10 gpg	10 gpg
pH	7.5	
Total Dissolved Solids (TDS)*	375	443

Based on inspection findings please find our recommendations and remarks:

1. The existing pressure tank is aged, but in working order.
2. The potassium permanganate filter is not working at this time.
3. Installing a water softener to treat the hardness found and noted in the quality results above would be beneficial.
4. I would recommend repairs to the electric conduit at the well head.
5. I would recommend having the iron filter serviced or replaced as it is not treating the iron effectively.

If you have any questions regarding these results and remarks, please do not hesitate to contact me.

Thank you,

John Jeffery, Owner/Operator

Well Contractor #7275

John Jeffery Well Testing and Consulting does not assume any liability for changes in quality or quantity from the date of this report forward.