Well Testing & Consulting

John Jeffery
Phone:(343)989 2377
johndjeffery@yahoo.ca
800 Larchwood Cres., Kingston ON

October 30, 2026

RE: Well Test and Inspection at 8900 County Road 2

A well inspection was conducted at the above-referenced property. This is a drilled well with a measured depth of 65 feet and a static level found at 14 feet at time of inspection.

A flow test was performed over a period of time at a rate of 6 gallons per minute while measuring drawdown and recovery. There was no drop in pumping pressure or volume so it was determined that this well is making a minimum of 6 gallons per minute at this time.

Quality:

Parameter	Raw Water	Treated Water
Iron	1	0.5
Sulfur	0	0
Hardness	18 gpg	15 gpg
pH	7.0	7.0
Total Dissolved Solids (TDS)	335 ppm	345 ppm

Based on inspection findings please find our recommendations and remarks:

1. The existing pressure tank is aged and rusting.
2. The existing Culligan water softener appears to be in working order, however it had no salt at time of inspection.
3. I would recommend installing a new pressure tank.
4. I would also recommend installing an ultraviolet light disinfection system to provide consistent bacteria free drinking water.

If you have any questions regarding these results and recommendations, please do not hesitate to contact me.

Thank you,
John Jeffrey, Owner/Operator