

Prepared for:		Date Issued:	July 26, 2026
Name	Gordon's Ltd.		
Address	2950 Route 29 Rd. Rideau Lakes ON		
Date Inspected:	July 23, 2026		
Description:			
Appliance	Wood Stove and Flue Pipe		
make	Fisher		
model	n/a		
Venting System	Masonry Chimney		
Findings:			
Inspection results show that the installation of this appliance and/or it's venting system does not meet the applicable standard. Corrections are needed to the following:			
Improvement is needed to the ember pad at the right side (8" to the side) in order to meet the current standard.			
Improvement is needed to flue pipe fastening (3 fasteners per connection) in accordance with the manufacturer's installation instructions.			
Improvement is needed to flue pipe orientation (condensate must drain within the flue) in order to meet the current standard.			
Improvement is needed to cleanout clearances (6" to combustibles) in order to meet the current standard.			
Other Comments and Recommendations:			
The data plate is not visible due to location, additional improvements may be needed.			
It is recommended that the appliance and its venting system are cleaned and inspected as often as is needed to ensure proper and safe operation.			
Inspector:	Jason Graydon	Signature:	
WETT #:	10510		

The report documents findings that were present at the time of the inspection. Compliance is referenced to currently published applicable codes and standards.

Grayspec Home Inspections services does not warrantee, guarantee or certify the proper functioning of the solid fuel burning appliance for any period of time because of numerous factors; usage, maintenance, concealed issues and items beyond the scope of a level 1 inspection. Grayspec Home Inspection Services does not accept any liability related to, or as a result of this inspection.

Thank you for choosing Grayspec Home Inspection Services.

www.grayspec.ca