



A1 Plumbing, Pumps & Water Treatment Inc

Jason Steele
2516 County Road 15
Picton, ON K0K2T0

(613) 847-3810
j.steele1973@yahoo.ca

INVOICE	#25547
SERVICE DATE	Apr 07, 2025
PAYMENT TERMS	Upon receipt
DUE DATE	Apr 07, 2025
AMOUNT DUE	\$282.50

SERVICE ADDRESS
272 Beachwood Rd
Greater Napanee, ON K7R 3L1

CONTACT US
224 North Murray St
Quinte West, ON K8V 6R8

(613) 398-0599
service@a1plumbingquinte.com

INVOICE

Services	qty	unit price	amount
Inspections - Well Flow Testing	1.0	\$250.00	\$250.00
Licensed Well Technician performs a draw down and recovery test of well to provide a production (well yield) rate. Includes visual inspection of well and pump system and report. Well flow rates are subject to seasonal change.			
Well type: 6" drilled in a pit.			
Well depth: 51ft 3"			
Static water level: 4ft 2"			
Reserve: 100 gallons delivered during the inspection.			
Production Rate: 5 gpm (good flow)			
Well Notes: Well should be brought to code to meet ministry standards.			
Pump & Pressure System Notes: Hooked up with a submersible pump. System hits a 20 gallon pressure tank with a good air charge. Next the system hits a 2x10 sediment filter and uv light. All treatment in service at time of inspection. No water softener present in the home. Uv light gets changed annually to ensure potable water at the fixtures.			
202502-0000-045			

Subtotal	\$250.00
Total Tax	\$32.50
HST ON (13%)	\$32.50
Job Total	\$282.50
Amount Due	\$282.50

See our [Terms & Conditions](#)