292669

1853834 Ontario Ltd.
O/A- Rick Loney Plumbing & Heating
P.O. Box 1261
Bancroft, ON. K0L 1C0
613-332-1210

03/02/22
Oil tank inspection
by Rick Loney

DATE: FEB 3/22

TAX REG. NO. / N° DE TAXE: 830191284

SOLD TO / VENDU À: EDNA MACKEY

ADDRESS / ADRESSE: 5641 BOULTIER RD

SHIP TO / EXPÉDIER À:

ADDRESS / ADRESSE:

| CUSTOMER'S ORDER / COMMANDE DU CLIENT | SOLD BY / VENDU PAR | FOB / FAB | TERMS / CONDITIONS | VIA |
|---|---|---|---|---|
| | | | | |

| QUANTITY / QUANTITÉ | DESCRIPTION | PRICE / PRIX | UNIT / UNITÉ | AMOUNT / MONTANT |
|---|---|---|---|---|
| | T.S.S.A. INSPECTION FORMS | | | 150 — |
| | | | TVH/HST TPS/GST | 19 50 |
| | | | PST/TVP | |
| | | | TOTAL | 169 50 |

STAPLES 81B

# INVOICE
# FACTURE

# FUEL OIL DISTRIBUTOR INSPECTIONS
## ABOVEGROUND TANKS ☑ INSIDE ☐ OUTSIDE

**REPORT NUMBER:** 2452

***NOTE: Inspection is limited to external observation of tanks and components in their operating position.***

| | 1st TANK | 2ND TANK |
|---|---|---|
| Type of Tank i.e. ULC-S602 | ULC-S602 | |
| Manufacturer | GRANBY | |
| Date of Manufacture or Age in Years | SEP. 2005 | |
| Serial No. | AA 249598 | |
| 1. Is the tank approved for its present use? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 2. Does the tank appear to have been installed in accordance with the fuel oil code, the certification document and the manufacturer's instructions? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 3. Are the tank vent and fill pipes properly installed and terminated? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 4. Is the tank equipped with a proper fill cap? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 5. Is the tank equipped with a proper gauge and overfill protection device (whistle)? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 6. Is the tank properly supported on a firm base? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 7. Is the tank support system in good condition, non-combustible and stable? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 8. If two tanks are joined, are they installed on a common slab? | ☐ Yes ☐ No ☑ N/A | ☐ Yes ☐ No ☐ N/A |
| 9. If two tanks are bottom connected, are they connected with 2 in. pipe? | ☐ Yes ☐ No ☑ N/A | ☐ Yes ☐ No ☐ N/A |
| 10. Is the system free of leaks or any signs of weepage? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 11. Is the tank and piping painted or coated to prevent external corrosion? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 12. Are burner supply/return lines free of compression fittings? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 13. Are burner supply/return lines installed above grade and protected or underground and chased? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 14. Are burner supply/return lines installed to code? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 15. Is an approved shut-off valve installed? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 16. Is an approved filter installed? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 17. Is the fill/vent pipe steel or galvanized construction? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 18. Is the tank located at least 2 feet from the appliance or is the tank protected from the appliance by a fire rated wall. **(for inside tank only)** | ☑ Yes ☐ No ☐ N/A | ☐ Yes ☐ No ☐ N/A |
| 19. **If required is the tank protected from vehicle damage?** | ☐ Yes ☐ No ☑ N/A | ☐ Yes ☐ No ☐ N/A |
| 20. **If required is the tank (over 2500L) protected with appropriate secondary containment?** | ☐ Yes ☐ No ☑ N/A | ☐ Yes ☐ No ☐ N/A |
| NOTES: (any "No" answers must be explained in this section and the affected equipment repaired, replaced or tagged. | | |

**COMMENTS:**

Technician's Signature: Rick Toney Certificate No.: 121022 Date: FEB 3/22

53834 Ontario Ltd.
/A- Rick Loney Plumbing & Heating
O. Box 1261
ancroft, ON. K0L 1C0
13-332-1210

# FUEL OIL DISTRIBUTOR INSPECTIONS
## APPLIANCES – COMPREHENSIVE

REPORT NUMBER: 2452

OWNER / OPERATOR: EDNA MACKEY

LOCATION: 5641 BOULTER RD TELEPHONE NO. 613-332-3347

OWNER'S ADDRESS (If different from above):

| | 1st. APPLIANCE | 2nd. APPLIANCE |
|---|---|---|
| Type of Appliance | WARM AIR FURNACE | |
| Manufacturer | KIERR | |
| Model | K4C-090 31 | |
| Date of Manufacture or Age in Years | APR. 2007 | |
| Size (BTU/Hr) | 88,000 | |
| Serial No. | 1001081 | |
| 1. Is the appliance approved? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 2. Is the appliance installed in accordance with the fuel oil code? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 3. Is the appliance being used in accordance with its approval? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 4. Is the appliance venting installed in accordance with the fuel oil code? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 5. Is the venting system free of defects, debris or corrosion | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 6. Is the vent sized properly? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 7. Is proper combustion and ventilation air openings installed? | ☐ Yes ☐ No ☑ N/A | ☐ Yes ☐ No ☐ N/A |
| 8. Is the installation free of indications of heat exchanger cracks, defects in the refractory, pot and/or heat shields? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 9. Are all limits and safety controls properly installed? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 10. Is the appliance installed with appropriate clearances from combustibles? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 11. Are the results of combustion analysis acceptable? | ☑ Yes ☐ No | ☐ Yes ☐ No |
| 12. If required, is there a proper chimney cleanout? | ☑ Yes ☐ No ☐ N/A | ☐ Yes ☐ No ☐ N/A |
| 13. Is the chimney properly lined? | ☑ Yes ☐ No ☐ N/A | ☐ Yes ☐ No ☐ N/A |
| 14. Is the vent liner fitted with proper flashing, cap and base T? | ☐ Yes ☐ No ☑ N/A | ☐ Yes ☐ No ☐ N/A |
| 15. If there is a sidewall vent attached to the appliance is it installed according to code and the manufacturer's instructions? | ☐ Yes ☐ No ☑ N/A | ☐ Yes ☐ No ☐ N/A |
| NOTES: (any "No" answers must be explained in this section and the affected equipment repaired, replaced or tagged). | | |

**COMMENTS:**

Technician's Signature: Rick Loney Certificate No.: 121022 Date: FEB. 3/22