

Well Testing & Consulting



John Jeffery

Phone: (343) 989 2377

johndjeffery@yahoo.ca

800 Larchwood Cres., Kingston ON

July 23, 2026

WELL TEST AND INSPECTION REPORT

Property Address: 2950 R29 Portland

A well inspection was conducted at the above-referenced property. This is a drilled well construction with a measured depth of 120 feet and a static level found at 11 feet at time of inspection.

A flow test was performed at a pumping rate of 6 gallons per minute while monitoring drawdown and recovery. There was no drop in pumping pressure or volume. It was determined that this well is currently making a minimum of 6 gallons per minute at this time.

Water Quality Results:

Parameter	Raw Water	Treated Water
Iron	1.5	0
Sulfur	0	0
Hardness	17	0
pH	7.0	
Total Dissolved Solids (TDS)*	465 ppm	485 ppm

Based on inspection findings please find our recommendations and remarks:

1. The existing pressure tank is in good condition and in good working order.
2. Both the existing water softener and ultraviolet light disinfection system are good quality and in good working order.
3. I would recommend installing a new, vermin-proof well cap and electrical conduit on the wiring.

If you have any questions regarding these results and remarks, please do not hesitate to contact me.

Thank you,
John Jeffery, Owner/Operator

Well Contractor #7275

John Jeffery Well Testing and Consulting does not assume any liability for changes in quality or quantity from the date of this report forward.