

Well Testing & Consulting



John Jeffery

Phone: (343) 989 2377

johndjeffery@yahoo.ca

800 Larchwood Cres., Kingston ON

July 20, 2026

WELL TEST AND INSPECTION REPORT

Property Address: 467 Denridge Road

A well inspection was conducted at the above-referenced property. This is a dug well construction with a measured depth of 20 feet and a static level found at 16 feet at time of inspection.

A flow test was performed by pumping 280 gallons of water from the well at a rate of 5 gallons per minute with no drop in static level. This well is maintaining a minimum rate of 5 gallons per minute at this time. However, the static level seems low for this time of year.

Water Quality Results:

Parameter	Raw Water
Iron	0
Sulfur	0
Hardness	18 gpg
pH	7.5
Total Dissolved Solids (TDS)*	245 ppm

Based on inspection findings please find our recommendations and remarks:

1. Both the existing pressure tank and ultraviolet light disinfection system are in good working order.
2. I would recommend installing a water softener to treat the hardness noted in the quality results above.

If you have any questions regarding these results and remarks, please do not hesitate to contact me.

Thank you,
John Jeffrey, Owner/Operator

Well Contractor #7275

John Jeffrey Well Testing and Consulting does not assume any liability for changes in quality or quantity from the date of this report forward.