

Well Testing & Consulting



John Jeffery

Phone: (343) 989 2377

johndjeffery@yahoo.ca

800 Larchwood Cres., Kingston ON

July 6, 2026

WELL TEST AND INSPECTION REPORT

Property Address: 4708 Wolfe Swamp Road

A well inspection was conducted at the above-referenced property. The water source is a drilled well with a measured depth of 160 feet and static level found at 38 feet at time of inspection.

A flow test was performed at a pumping rate of 8 gallons per minute while monitoring drawdown and recovery. It was determined that this well is currently making 5 gallons per minute.

Water Quality Results:

Parameter	Raw Water
Iron	trace
Sulfur	0
Hardness	28 gpg
pH	7.5
Total Dissolved Solids (TDS)*	1110 ppm
TDS through RO tap	345 ppm

Based on inspection findings please find our recommendations and remarks:

1. The existing pressure tank is in good condition and in good working order.
2. The existing ultraviolet light disinfection is good quality but is due for annual service.
3. The Reverse Osmosis is due for the filters to be changed. The TDS are elevated.
4. I would recommend installing a water softener as it would be beneficial to treat the hardness noted in the quality results above.

If you have any questions regarding these results and remarks, please do not hesitate to contact me.

Thank you,

John Jeffery, Owner/Operator

Well Contractor #7275

John Jeffery Well Testing and Consulting does not assume any liability for changes in quality or quantity from the date of this report forward.